

Ladder from Taiwan

Test & Inspection


Rachid Nouicer, Milan Stojanovic

Bench Test South Side

South Side (Module 51) / Bias = 100V at Taiwan

Module 51 with bias

Chip voltage: 3.6V, Chip current: 0.515A
Bias voltage: 100V, Bias current: 0.4 μ A




We observed one chip with half entries, U23

South Side (Module 51) / Bias = 100V at BNL


Current A = 140 nA

Current B = 110 nA


Calibration



Amplitude vs Channel



Number of entries




We observed two chips with half entries, U23 & U12

Bench Test North Side

North Side (Module 264) / Bias = 100V at Taiwan

Module 264 with bias

Chip voltage: 3.6V, Chip current: 0.519A
Bias voltage: 100V, Bias current: $2.4\mu\text{A}$




Sensor B has a high current

North Side (Module 264) / Bias = 100V at BNL


Current A = 220 nA

Current B = 2.3 μ A


Calibration



Amplitude vs Channel



Number of entries




Similar high current has been observed at BNL for sensor B

Visual Inspection at BNL



Visual Inspection

- The ladder safely arrived at BNL
- One new chip has half entries, possibly because of the transportation damage





Visual Inspection

- Lot of fibers observed on the chips





Visual Inspection

- Lot of fibers observed on the chips




Visual Inspection

- Wire bonding can be improved



Visual Inspection

- Encapsulation on the sensor → needs improvement,
- concern: it seems that height of encapsulation is bigger than 1.2 mm




Visual Inspection


➤ Gluing issue: Big concern!

- We didn't observe the glue between the two adjacent HDIs nor between the HDIs and the stove
 - This implies the ladder will run hotter than BNL ladder

Taiwan Ladder



BNL Ladder



Taiwan Ladder Box

- The box is READY to be shipped back to Taiwan

