

# Progress Report

RIKEN/RBRC

Itaru Nakagawa

# Scope for Readout Review

- HDI (Itaru)
  - Production Status
  - [Thruhole quality control \(Outside the scope?\)](#)
  - Performance
- Bus Extender (Takashi, ...)
  - Length optimization (Dan, Rachid)
  - Preproduction fabrication (yield rate, thruhole, peel strength issue, etc..)
  - Electrical Performance
    - TDR (Kondo-san)
    - S-parameters (Kondo-san)
    - BER (Kondo-san?)
    - Eye-diagram (Kondo-san, Morita-san)
    - Actual data transmission ([Half entry issue](#))
  - Mechanical Performance
    - Radiation resistance (Hikaru Imai/Takashi/Itaru)
  - Production Plan and Schedule (Takashi/Itaru)
- Conversion Cable (Itaru)
  - Curving Design (Dan)
  - Column-B,D (Itaru)
  - Production Plan and Schedule
- ROC (Itaru)
  - Regulator & replacement plan and schedule
  - 1008 ROC performance test status
- [FEM & FEM-IB \(Outside the scope or should be addressed as a back up of FELIX solution?\)](#)
- [Data Acquisition \(Outside the scope because It's a part of FELIX? Otherwise we can only report about 2018 beam test.\)](#)
- Slow Control & Debugging Tools
  - Readbacker for standalone (Takashi) and 1008 (Itaru)
  - Interception board for debugging (Itaru)


# Half Entry Issue Debugging Strategy

1. Data analysis of the observed waveform ( $\mu$ , YA, Taskahi, IN)
  - Waveform comparison
  - Eye diagram
2. Individual Chip Reset (**Genki, Yasuyuki**)
  - Keep resetting only the FPHX chip causes the half entry. Rests are to be remain un-reset between Runs.
3. Phase Follower Tuning at ROC-FPGA
  - FPGA code was developed in Taiwan and available for testing
  - Prepare ROC board for this testing. Another test bench ROC board to be dedicated for this study. There is potential risk we cannot re-install the original code to the ROC data FPGA. 3V regulator is to be installed to the ROC.
  - In the meantime, wait for #1 analysis

# Stave Status

- Continue attempts using DP460, not DP460"EG" following Rob's instruction
- Although Asuka hasn't been demonstrated yet to achieve 1Nm torque test, the contract is being proceeded not to introduce further delay for batch-3.

Rob's Instruction



Lightly clean away some graphite glue to increase surface area for DP-460. I made 2 small channels on either side of the tube. Be gently. This is just to remove a little of the loose graphite epoxy. I use the scribe below followed by a Fiberglass Scratch Brush



The 3<sup>rd</sup> batch concept is the minimum number of staves to save the lead-time. Rest of production to complete the total ladder assembly is to be followed afterword. In the meantime, we'll estimate how many more to be fabricated.


# 3<sup>rd</sup> Batch Stave Production

Stave Status		Layer-1		Layer-2		Layer-1+2
		Survived	Shortage	Survived	Shortage	Shortage
BNL	Assembled	18		6		
	Not Assembled	0		20		
Taiwan	Assembled	0		2		
	Not Assembled	1		24		
# of Staves BNL + Taiwan Available		19		52		
# of Ladders to be needed for 1008 barrel		24	5	32	0	5
# of Ladders to be needed for Spare barrel		24	24	32	12	36
<b># of Ladders needed for 1008+Spare</b>		48	<b>29</b>	64	<b>12</b>	<b>41</b>
<b>3rd Batch Contract (Tentative)</b>			<b>16</b>		<b>16</b>	<b>32</b>
4th Batch Contract			?		?	?

Not tested yet

Not tested yet


# Stave Production Schedule



# HDI Status

Optimization of thicker thruhole copper plating is in progress (15~18  $\mu\text{m}$   $\rightarrow$  20~22 $\mu\text{m}$ )  
1<sup>st</sup> batch delivery is still scheduled on June 28<sup>th</sup>.

U6



U9

