



A Proposal for INTT Beam Clock Distribution System

RIKEN/RBRC
Itaru Nakagawa






FVTX Packet Drop Issue


FVTX Packet Drop Off Issue

PHENIX Run15 FVTX Online Monitor





Non negligible fraction of the acceptance are suffered from "low rate" issue

Packet Drop Off History in a give run




Some packets stops sending data in the middle of run. Once this occurs, the packet won't be recovered until the electronics are reset in the beginning of run routine.

Investigation of packet drop out




FVTX group tried to correlate with the humidity, but it wasn't too conclusive. They were not able to observe the smoking gun, but their latest understanding of the cause is a glitch in receiving beam clock (BCLK) signals in ROC.


FVTTX Beam Clock Distribution Configuration





FVTTX Beam Clock Distribution Configuration



FVTTX Beam Clock Distribution Configuration






BCO cables ended up with 1.8 *meter* long to reach the ROC board on the far end

Summary for packet drop off issue

- FVTX suffered from the packet drop issue throughout their operation every year.
- May or not may not be correlated with humidity.
- The current suspect is the long and unshielded BCO cable supplied to ROC, but FVTX crews were not able to observe the smoking gun.
- It is highly possible the INTT will be suffered from the same issue if we don't make any action for this since we use exactly the same RO system from FPHX to ROC as FVTX.

Proposed Beam Clock Distribution Config.



Keep the electric section as short as possible.
 Employ high class ethernet cables for the
 better noise shielding performance



Ethernet Cable Category

Cat5



Cat6




Cat7




Cat8




Category-8




CAT5e UTP Bulk Cable






CAT6 UTP Bulk Cable




CAT6A UTP Bulk Cable




Category Cable Wiring



Better shielded




BCDB Location?




Takashi's Idea



Perhaps behind ROC Board



Beam Clock Distribution Board




BCLK CABLE FOR REGULAR ROC


1	2	3	4
8	7	6	5

1	7	6	4
8	2	3	5

BCLB Schematics




BCO CLCK






* Similar for START CLOCK

Proposed Modification



Unnecessary fan outs




Ethernet Connector

Custom made BCO cable



No upgrade needed to ROC



Courtesy of Genki

Production Cost

- Need 16 BCDBs + Spares ~ 20 BCDBs
- Waiting for a quote from a Japanese Company.



Summary

- As one of the solution for the packet drop off issue, a modification idea to BCLK distribution system is proposed.
- Following the advice from FVTX expert, the electric signal section is to be kept as short as possible ~10cm or so.
- The BCO board is to be thus assigned an independent board per ROC and the optical splitter will be used to deliver input BCO and START signal to each BCO board.
- Employ CAT6 or higher instead of the current twisted pair flat cable.
- Quote is in progress for the independent 20 BCO boards.