

Solution for A1 Port Analogue Regulator Wrong Grounding

RIKEN/RBRC
Itaru Nakagawa

On 2022/03/23 10:40, Brooks, Melynda wrote:
Hi Itaru,

Yes, the grounding is a mistake. The primary result of the mistake is that the non-diagonal wedges needed to be calibrated in pairs so that the grounds got connected correctly when calibrating. Other than that, function was okay.

Melynda

From: Itaru Nakagawa <itaru@riken.jp>
Date: Thursday, March 17, 2022 at 4:53 AM
To: Melynda Brooks <mbrooks@lanl.gov>
Cc: jin huang <jhuang@bnl.gov>
Subject: [EXTERNAL] Column-A Station-1 port of FVTX ROC board

Dear Melynda,

I know it is getting past for you, but I have to bother you again. I found mysterious circuit design in the ROC and I need to confirm with you. See attached summary file. The issue is in the analogue regulator for the FPHX of the A1 port (Column-A, Station-1). The ground of the regulator suppose to be wired to AGND_4 I believe, but it is actually wired to AGND_2. It is hard to imagine the circuit was designed like this on purpose. As I commented in slide 6, I guess it didn't cause severe effect for FVTX, but I would appreciate if you aware of any misbehavior of wedges connected to the A1 port commonly. I am seeking for any portable solution to fix this because I am afraid our condition can be different from FVTX. If you have any suggestion or idea, I also appreciate.

Best regards,


-itaru

Voltage Gap Measurement with Small Wedge




FVTX Small Wedge

Present Circuit Diagram



FVTX Case Circuit Diagram



$$i_{A0} \neq i_{A1}$$


The voltage drop between PS and the regulator is not necessarily same between A0 and A1.

$$\Delta V = 5.406 \text{ V}$$

$$\Delta V = 0.0001 \text{ V}$$

This is acceptable.

FVTX Case Circuit Diagram



The drawing current can be different with/without **FVTX Small Wedge** though, turns out the voltage drop different between A0 and A1 ports are negligibly small. Presumably because the analogue current draw is relatively small compared to digital to begin with.



$$\Delta V = 5.413 \text{ V}$$

$$\Delta V = 0.0001 \text{ V}$$



Implementation of FVTX small wedge may not be crucial to operate A1 port.

Calibration

Without J1 power cable Without small wedge






Without J1 power cable Without small wedge



Same condition, but different take.
Thus floating analogue ground doesn't secure stability.

With J1 power cable With small wedge





Observed something similar without small wedge.

Next Step

- A1 port operation together with J1 power cable seems to work regardless of small wedge plugged in or not.
- We only need to connect analogue ground cable of A0's U614 regulator. No need to power other regulators in B0, C0, D0 . Better to make dedicated cable.
- Better to confirm the silicon response with source.

Input Voltage Anomaly for A1 Analogue Regulator





Voltage scan of the input/output voltage of analogue power regulators for FPHX at ROC



NW4

Circuit Design

Traced back circuit for the analogue regulator for A1 port in the ROC circuit drawing.






+2.5V V_{out} and AGND

Analogue

Digital




A1 port



| Regulator | +2.5V_AX | AGND_X |
|-------------|----------|----------|
| U614 | 0 | 0 |
| U615 | 1 | 1 |
| U616 | 2 | 2 |
| U617 | 3 | 3 |
| U618 | 4 | 2 |
| U619 | 5 | 5 |
| U604 | 6 | 6 |
| U605 | 7 | 7 |


AGND_2 is wired to U616 as well

AGND_2 Trace on ROC




J1 port
(FPHX Power for Station-0)

Calib-Multiplexer for Column-A




DF18 for Column-A, Station-0





Evidently, there is mis-match in the analogue GND. Station-0 and Station-1 are mixed.

AGND_6 Trace on ROC




DF11-200P-2DSA


J1A port
(FPHX Power for Station-1)



Calib-Multiplexer for Column-C




DF18 for Column-C Station-1



AGND is wired within Column-C, Station-1 throughout ROC trace as expected.


AGND_4 Trace on ROC




DF11-200P-2DSA

J1A port
(FPHX Power for Station-1)


No regulator is wired from AGND_4



Calib-Multiplexer for Column-B




DF18 for Column-A Station-1





The AGND_4 analogue ground is not wired to any regulators.


AGND_2 Trace on ROC




J1 port
(FPHX Power for Station-0)



Calib-Multiplexer for Column-A




DF18 for Column-A, Station-0



AGND_2 is shared with Column-A, Station-0 and Station-1 analogue regulators.


FVTX Case Circuit Diagram



AGND is provided by A0 power supply which is likely to be shared with the GND of A1 analogue power supply. This circuit effectively secures stable operation of U618 regulator presumably.

Not sure how stable U618 regulator output is with the floating ground with open J1 and DF18(P100,P101) for INTT case. It is not guaranteed INTT works as well as FVTX.

How can we recover?




Disable AGND_2 connection and Install new jumper cable.

Need to bridge between primary side and back side of the ROC boards. This is not trivial recovery. Keep searching for more portable solution.


Actual voltage measurements

Column-C1 Analogue Regulator Measurement


Interception Board & V_{out}

| PS [V] | Current [A] | C1876 [V] | C1875 [V] | Intcpt Bd. [V] |
|--------|-------------|-----------|-----------|----------------|
| 1.5 | 0.00 | 1.5 | 0.8 | 0.8 |
| 2.0 | 0.05 | 1.9 | 1.8 | 1.8 |
| 2.5 | 0.07 | 2.3 | 2.2 | 2.2 |
| 3.0 | 0.09 | 2.9 | 2.8 | 2.8 |
| 3.5 | 0.09 | 3.2 | 2.8 | 2.8 |
| 4.0 | 0.09 | 3.8 | 2.8 | 2.8 |
| 4.5 | 0.09 | 4.5 | 2.8 | 2.8 |

- Connected only J1A Channel 11,12
- Ladder + 40cm conversion cable on C1 port
- Voltage meas. at U604 & Interception Board
- Observed 0V for digital power at Interception Board




Column-A1 Analogue Regulator Measurement



The output voltage at analogue regulator is 2.8V.
Observed +0.4V higher voltage at the interception board.
Presumably it is caused by the ground level difference.

| PS [V] | Current [A] | C1920 [V] | C1919 [V] | Intcpt Bd. [V] |
|--------|-------------|-----------|-----------|----------------|
| 1.5 | 0.00 | 1.3 | 0.44 | 0.58 |
| 2.0 | 0.03 | 2.0 | 1.2 | 1.3 |
| 2.5 | 0.06 | 2.2 | 1.9 | 2.2 |
| 3.0 | 0.09 | 2.5 | 2.4 | 2.7 |
| 3.5 | 0.10 | 3.1 | 2.8 | 3.2 |
| 3.9 | 0.11 | 3.4 | 2.8 | 3.2 |
| 4.5 | 0.11 | 4.0 | 2.8 | 3.2 |

- Connected only J1A Channel 3,4
- Ladder + 40cm conversion cable on A1 port
- Voltage meas. at U618 & Interception Board
- Observed 0V for digital power at Interception Board




NE3 Analogue Power Trace Resistance

Only J1A Ch-3,4 cables are connected to PS




C1



Analogue GND Line is directly connected to AGND of Interception board

A1




Analogue GND Line is **not** directly connected to AGND of Interception board

Barely conducted and unstable
~4kΩ!?

NE3 Analogue Power Trace Resistance

A1


Interception Board



No ROC Power Cable Plugged in


A1

Interception Board




ROC Power Cable Plugged in, but not powered

NE3 Analogue Power Trace Resistance



ROC Power Cable Plugged in, Power On



ROC Power Cable Plugged in, but not powered