

# 260-L LAr System Progress Report

Yichen, Sergey


8/16/22




# Lab Safety

- COVID level in Suffolk County is still at HIGH and expected to be in the same level in the next weeks
- Please follow COVID protocol wearing face mask
- Watch out for the summer students and interns
- Take the additional trainings required for all employee Ethics and Privacy by 9/2; Active shooter training by 9/30

# Plumbing for filling



# Plumbing for sampling



# Filling Preparation

## ▶ 260-L system pump-and-purge


- The main dewar+ullage condenser+purifier volumes are pump-and-purged 4 times before filling

## ▶ Filling hose(downstream of inline filter) flush

- The hose between inline filter output and main dewar are flushed with GAr flow from the main dewar for ~3 hours in total (Not pumped)
- Pump failure at the last pumping stage at with 0.2 psi residual pressure(~0.05 psi with the pressure transducer when pump down to  $\sim 10E-4$  Torr)
- Pump cannot even powered on after the failure, accidentally fixed on the next day. Still malfunctioning randomly

## ▶ Filling hose (upstream of inline filter) flush

- Upstream of inline filter purged with Ar vapor from the supply dewar



**pump-and-purge**

# Filling Preparation

## ▸ Sampling tubing from gas panel


- It is known that the plumbing has been flowed with extremely high humidity gas at the beginning stage of the activation with moisture analyzer saturated
- The full length of the tubing from the gas panel to the joint at the analyzer wrapped with heating tape
- Due to the length of 20+ ft, 3 individual heating tapes installed to cover the full length, each controlled with a variable transformer
- The section of tubing was baked to  $\sim 80$  C for 2 hours with GAr flow to the gas panel vent
- It seems to be insufficient by the later observation



# 260 L System Filling

## ▸ 260-L System filled with LAr passing inline filter


- It was found both of the capacitance level gauge and press differential level gauge are not functioning properly
  - The calibrated coaxial cable with the capacitance level gauge was replaced with an unlabeled shorter cable
  - Differential level gauge is not output voltage signal
- LAr level readings can be indirectly tell with the RTD temperature probe with 6 RTDs in equal intervals
  - LAr immersed the first 2 RTDs, lower than the 3rd one
  - LAr is estimated to filled 30% of the dewar height
- The level gauges needs to be fixed in the future run





# 260-L Cryogenic Operation

## ► Cryogenic operation running smoothing for 6 days


- Continuous batch fill between 80-50% of condenser volume
- Filling cycle is about every 1.75 hrs
- LN2 supply from the 6000 gallon tank
- Refilling time of LN2 portable dewar is about 20-30 mins
  - Two refills have been conducted
  - 2 portable dewars refilled each time to save LN2
- 6000-gallon LN2 tank boiling off is very low, still ~40 Psig pressure after the recent refill (Relief pressure is 50 psig)








# Gas analyzer readings with periodic variation



# N2 analyzer reading with flow rate

- ▶ **N2 analyze requires a very small flow rate 75 cc per meter**
  - It was found with system run with  $\sim 15.2$  psia, the N2 flow rate is below the require flow rate
  - Increase the LAr pressure to increase the flow rate to 75ccpm
  - N2 reading stabilized to a constant, except for the spike at the filling
  - The flow rate on reading on when sampling with the tube in LAr is almost 0,  $<1$  ccpm



# Summary of observations

- The commercial Ar supply quality from this delivery is slightly worse than others
  - [H<sub>2</sub>O]~1 ppm, [O<sub>2</sub>]~600 ppb,[N<sub>2</sub>]~0.8 ppm
- The impurity concentrations after fill is high after fill from line filter
  - [H<sub>2</sub>O]~90ppm, [O<sub>2</sub>]~1.0 ppm, [N<sub>2</sub>]~1.0 ppm
- The impurity concentrations improved with time
  - [H<sub>2</sub>O]~800 ppb, [O<sub>2</sub>]~100-200 ppb,[N<sub>2</sub>]=0.6 ppm
- N<sub>2</sub> analyzer reading stabilized to a constant with required sample gas flow rate 75 ccpm achieved

# Lesson Learned

- Gas panel + all fresh tubings should be baked
- The baseline contamination level of the system should be measured before filling
- Should implement plumbing flush system to keep the analyzers at baseline readings
- Orifice size of the liquid sampling tube is too small to maintain sufficient flow rate for gas analyzers
- The new 260L system with large volume and fresh plumbings has less fault tolerance than the 20L system

# Equipment to be replaced/fixed

## ▶ **Equipments to be replaced**

- Vacuum pump 10+ yrs old should be replaced.

## ▶ **Malfunctioning equipments**

- Differential liquid level-gauge is not responsive to level change
  - Need to order a replacement
- Capacitance LAr level-gauge readings are incorrect
  - The calibrated coaxial cable was missing
  - Inquiring with the manufacture for new calibration or new probe+cable
- LAr heater damaged in the heating test before filling
  - Should use mechanic connection for cables instead of soldering
  - Going to order a new one from KHV

# Next Steps

## ▶ **Cryogenic operation**

- Running for another week
- Baking the sampling tube
- Refill with LAr through inline filter with residual LAr
- Warm up

## ▶ **Filter regeneration**

- The inline filter needs to be regenerated next

## ▶ **Tubing baking system implementation**

## ▶ **Analyzer flush system**

## ▶ **Get the replacement parts**

- New heater from KHV
- New diff-level gauge
- New or re-calibrate capacitance level gauge

## ▶ **Revise operating procedures**