



Status of machining of tiles at UCR

Miguel Arratia,
University of California, Riverside





How we manufacture the cells at UCR

From EJ 212 raw material (square 10x10 cm²), we get ~8 small cells. These are milled while in a custom vacuum chuck.




Polishing & Painting



Edges & dimple are hand polished,
Edges painted with Saint-Gobain BC-621 paint




Machined tiles looked beautiful at first



But after a while (weeks), we started noticing crazing




Likely culprit: Traced that our machine shop was using standard coolants , and “scraping” piece afterwards by hand.



New method: submerge in water while in vacuum chuck

we got rid of most obvious culprits (we are not using chemical coolants, or compressed air, or alcohol, or clamping of any sort)




the dimple: They are using a ball nose end, at about 7500 rpm, 55 inches a minute. 0.001 inch chip thickness

Bad news, newer method still produces crazing (but later than old method)




Miguel Rodriguez 5:04 PM

There are many scintillators created last week done by the old method in the clean room that are already showing crazing. This doesn't apply to the ones created in the new method.

IMG_4694 ▾







Batch made with refined method (submerged in water for cooling, no compressed air) shows this level of crazing after ~1 month



Got the idea of annealing tiles from work by CEPC/CALICE on SiPM-on-tile strip ECAL

Scintillator modules



We suspect that annealing of the scintillator might help with the crazing

We used our climate chamber to test approaches




First try at annealing (48 hr, 80 C)



Some warping seen in the scintillator tiles (right one)

→ This was too much

First try at annealing (48 hr, 80 C), continuation




Crazing is gone, but some texture appears

→ This was too much.

We also changed the resting surface to soft cloth (from plastic)



Second try (12 hr, 80 C)



Some warping seen in
the scintillator tiles
(right one)



→ This was too much

Second try with another pair (12 hr, 60 C)





No warping or texture added to scintillator but crazing still there

Before and after annealing (4 hr @ 80C)



Crazing goes away with annealing, no evident trace of it. We will keep the tiles using these tests under observation

No noticeable warping or texture in the scintillator with the annealing (4 hours, 80 C)



Summary

- Current method for machining EJ-212 is with CNC, water-only coolant, custom vacuum chuck (to avoid clamping), and no compressed air or any other chemical.
- Still, some crazing is visible some time after machining them.
- After some iterations, we found that 4 hr @ 80C of annealing removes the visible effects of crazing and has no secondary effects (like warping or additional textures)