




# SPHENIX INTT

## - Weekly Report

Cheng-Wei Shih,  
Chia-Ming Kuo

National Central University


2021/10/1




# Testbench system in radiation lab



- The set up of Testbench system in radiation lab is finished.
- The system can take source data with Sr-90 and calibration data.



External trigger mode      GND cable on support




By switching **FEM-IB**, **PCIE cable** and **PC**, we can have 2 Testbench systems, one in 923 (calibration test) & one in radiation lab (source test)

# Source test result



- Plan :
  - External trigger mode.
  - Sr-90 fixs at middle of ladder in transverse axis, and stays at each chip for 4 mins.



At least 1 event for each channel

# Summary




- Source test :
  - The set up of Testbench system in radiation lab is finished.
  - 4 mins for each chip is enough to make sure at least 1 signal for each channel under current setup.
  - It takes ~ 2 hours to finish the source test for one ladder.
- 15 ladders assembled in Taiwan. C-1 : 11 ladders
- We are moving to next half-ladder assembly session.

# Back up




# Taiwan INTT team



Ou-Wei Cheng



Kai-Yu Cheng




Chia-Ming Kuo    Cheng-Wei Shih    Lian-Sheng Tsai  
Wei-Che Tang    Rong-Shyang Lu    Jenny Huang

# Source test result


- Self-trigger (silicon signal ==1 → FEM signal =1)

Sr-90, source position fixed at U8 & U7    adc0 is set at 40 to reduce the noise (original adc0 : 15)



- External trigger (silicon signal ==1 && sci signal ==1 → FEM signal =1)

Source fixed at U8 & U7    adc0 is set at 25 to reduce the noise




Some chips around the edge seems to be noisy

# Source test result


- External trigger (silicon signal ==1 && sci signal ==1 → FEM signal =1)

Source move along the HDI

adc0 is set at 25 to reduce the noise



Fishbone behavior



- The fishbone behavior appeared when the motor is in operation.
- JP group also saw this behavior before.
- It seems to be the problem from GND.
- Possible solution : connecting a ground wire to mechanical support