

# ROC Status

On behalf of Kazuma Fujiki

# ROCs in RIKEN

F: Fiber Latch Issue (often TLK is the cause)  
H: Half Entry  
R: Repaired

	ROC #	FVTX	Regulator Upgrade	TLK Replacement	Location	Class	Barrel	A1	A2	A3	B1	B2	B3	C1	C2	C3	D1	D2	D3
22	21	26	SE3	✓	RIKEN	4		F	F	F	F	F	F	F	F	F			
23	22	5	-	✓	RIKEN	4		F	F	F	F	F	F	R	F	F			
24	23	11	-	-	RIKEN	4		H	F	F	H	F	R	F	F	F	F	F	R
25	24	21	-	✓	RIKEN	2		R	R	R	R	R	R	R	R	R	R		

- ROC21 repair work has been reasonably successful. Can be shipped to BNL up on necessity
- ROC5 will be provided to LANL