# Production Status

RIKEN/RBRC

Itaru Nakagawa

ROC Debugging

Fiber Sync Error Debugging with John K.

Debugging in progress

Comma words observation by John and Raul

Bad port

good port

Bad port

good port

Indeed the comma words for bad ports are collapsed. However, we didn't observe anything suspicious in the eye diagram of bad ports. No extra jitter was observed compared to good port.

Collaboration Meeting

Doodle

https://doodle.com/meeting/participate/id/avgARyVb

Collaboration Meeting Draft

- Barrel Assembly (Rachid)
- Barrel Test (Genki)
- Grounding Configuration (Rob)
- INTT Power System (Ivan)
- 1008 ROC Repair Status (Itaru)
- INTT Ladder and Beam Test Unresolved Issues (Cheng-Wei)
- Cosmic Ray Measurement at NWU (Yumika)
- Low level semi-online/offline software (Wei)
- Online Monitor (Joseph)
- Expert-GUI (Hikaru)
- ROC FPGA (Takashi)
- …

Open Issues

	Issue	Plan
m-coax	Partial data drop	Modify ROC slow control FPGA to make the readbacker working
ROC	Data Fiber Latch	Serializer debugging with John K.
ROC	Unfunctional Calibration Pulse	Re-download ROC Slow Control FPGA