ICARUS Cathode Nonplanarity

Lane Kashur
26 September 2024

Colorado State University

Detector Calibration

Cathode Nonplanarity

ICARUS's stainless steel cathodes are <u>not</u> perfectly planar

- Some parts bent up to 2 cm
- Similar issues seen in other LArTPCs

This has been seen to negatively impact track reconstruction efficiencies

<u>Solution</u>: Create topographic map of each cathode in order to model in simulation

i.e. Change $x_{cathode}$ = constant to $x_{cathode}$ = f(y,z)

Detector Calibration

Cathode Nonplanarity

EE TPC

EW TPC

Detector Calibration

Cathode Nonplanarity

WE TPC

WW TPC