



EIC Project request: inner detector maintenance without beam vacuum break




Side View

dRICH "storage" position may allow access to the barrel, otherwise splitting into halves is necessary



Top View

The real conflict is with the enlarging beam pipe downstream



An asymmetric dRICH bore could be the solution, to be validated with simulations

