



Last Week at RHIC









Time (Start Fill = 34655)

RHIC status and Lumi Projections

111x111 physics running since 4/30. Preliminary luminosity accounting







RHIC Status

- MD on 6/18, 6/21, and 6/25
 - ▶ MD on 6/18 unsuccessful, conferred with Al for recommendations following MD
 - ► 6/21 developed ramp with polarity swap. Updated optics for magnet transfer functions to what was used in Run15.
 - ► MD today to revisit MD on 6/18
- IR8 DH0 polarity swapped on 6/20 Maintenance day to support 0→2 mrad crossing angle
 - dedicated run with sPHENIX at 0 mrad on 5/24
 - ► sPHENIX and STAR at 0 mrad following dedicated run
- Power dip during maintenance day resulted in a prolonged recovery
 - ► BA1 QEI replacement
 - ► YA2 QEI error, found tripped breaker to reset
 - ▶ yellow injection kicker comm error, DG645 reset
 - ▶ yi11-tq5 replaced
- yellow polarization lifetime poor due to Qv near 7/10, ongoing optimization
- · With optics change, in a better position to deliver higher luminosity with equivalent intensity
- This is a new setup so need to iterate on tunes to optimize beam lifetime and polarization lifetime at store

