

Diameter uniformity along the z-direction (up to 1 inch) and and ϕ







The variation is negligible







We modified the 8020 setup to install the end rings



The shaft is aligned with the motor line

The 3 front legs need to be better aligned