


Back to Physics

- Nominal store performance
- An extended failure of YA2 RF station affected stores Saturday until a repair could be made
- A failure of an internal component of MP7 over the weekend forced an unexpected change to MP6 Monday, intensity fully restored Tuesday



Moving ahead

- Physics and fast turnaround times
- Maintenance Thursday
- 56 MHz test ramp Friday

