

Run24 Preparation

# INTT Team Leader for Run24

- Hardware : Rachid
- Commissioning/Physics : Genki
- Spin Coordinator : Itaru

# Requirements for Run24

- Hits are dropped in the official decoder has to be fixed before Run24.
- Reconstructed z-vertex inconsistency between MBD and INTT needs to be fixed.
- Establish 1BCLK Timing
- Event mix up needs to be fixed
- Calibration and database
- Online monitor
- Establish how to remove crone hit events.
- Debugging options of DAQ ( associate over low tag FPHX, ROC, FELIX with DAQ errors)
- Expert GUI and Online parameter database