



Last Week at RHIC








RHIC status and Lumi Projections

111x111 physics running since 4/30. Preliminary luminosity accounting





RHIC Status

- physics running with up to 2.0e11/bunch at store
- RHIC has been ODH1 for the last week, requiring additional work planning and PPE for entrance
- Maintenance Thursday, 6/20
- cold snake has increase heat load
 - unpolarized protons used Wednesday-Saturday.
- Friday | limited polarization optimizations to maintain helium reserves
 - QLI from y12-dh0-ps voltage dip caused QLI, rezeroed 12a-qd2 quench bucket
 - y6-q89-ps replacement
 - y10-qd-psw, AC-DC converted for main contactor replaced

Saturday high beam losses on b6-lm3.2

 H-jet bump collapse timing change resulted in collisions at IP12 from orbit overshoot when going to goal

Sunday

• correctors in alcove 5c tripped due to a bad relay on blue interlock system