

18 June 2025

- Nick services request
 - Roland WIP updating TOF and cymbal and other services changes. Can share current doc, but may need thorough changes also
- Common Links
 - EPIC Wiki <https://wiki.bnl.gov/EPIC>
 - EIC Sharepoint (can access from Wiki Si Vertex Tracker Page)
 - <https://brookhavenlab.sharepoint.com/sites/EICPublicSharingDocs/Shared%20Documents/Forms/AllItems.aspx?id=%2Fsites%2FEICPublicSharingDocs%2FShared%20Documents%2FExperimental%20Program%2FEPIC&viewid=991e5a0b%2Dd053%2D4acd%2D8565%2D2cc07a440143&p=true&ga=1>
 - General Documents, ePic.Interface Control Document Excel for Services
 - Roland works here, don't edit without permission
- Ernst has more electrical services comparison insights that might help guide efforts. Slide “Comparing the areas for electrical services” – just an estimate
 - Notes on outer barrel and disks
 - Will write it up over a few days and send to Roland