## AGS Status: Time meeting 4/22/25

- Extraction BLW supply work continues
  - Modifications expected to be finished by ~Apr
    23
  - Designed to protect against overvoltage conditions on the transistor bank
- L20 Septum failure preventing injection into AGS
  - Repair estimated by Friday.
- AGS Tune meter: intermittent failure of horizontal kicker supply
- Polarimeter signal cable problem resolved
- Booster studies
  - ORM for AI/ML optimization
  - Space charge/emittance studies

## Injector intensities



