



AGS Status: Time meeting 5/13/25

- Extraction BLW supply work continues.
 - G09 to be connected back to ring today for testing
 - H11 processor problem, to be replaced by a PLC, ~1 week estimate
 - Alternative plan: if Memorial Day weekend approaches and H11 not ready, power the full bump with G09 only (a la late Run 24)
- Development
 - Skew quad res correction setup on the split/merge user
 - AI/ML work on the proton merge
 - Progress on tune meter upgrade with BBQ pickup in triggered mode


Injector intensities




AI/ML Correction of Proton Flattop merge



As found



Intentionally detuned



Reinforcement learning corrected
(one iteration)

AGS tunes with BBQ pickup

