

Half-ladder 390, Half-ladder 394, stave 02-0118

Ladder - channel classification

Number of total bad channel :

# of bad channel	percentage	class
2	0.0%	Class-1


Ladder - bonding

Number of total un-bonded channel :

# of un-bonded channel	percentage
0	0.0%

Stave - 02-0118

| torque : passed | leakage : 0.042 psi | flow : 0.806 psi | flatness : 95.1 μm |




NOTE

Nothing

Half-ladder (N) : 390

of bad channel : 0
Nothing


of un-bonded channel : 0
Nothing




Half-ladder (S) : 394

of bad channel : 2
U7-18, U16-120


of un-bonded channel : 0
Nothing




Sensor 1185(N,A)



Sensor 1185(N,B)



Sensor 1179(S,A)



Sensor 1179(S,B)

